1.	PRODUCT AND COMPANY			
Product Name: Company Name:	Goof Off Goodbye Cracks W. M. Barr 2105 Channel Avenue Memphis, TN 38113	Phone Number: (901)775-0100		
Web site address: Emergency Contact: Information: Intended Use:	www.wmbarr.com 3E 24 Hour Emergency Contact W.M. Barr Customer Service Repair of cracks in plaster, drywall, an	(800)451-8346 (800)398-3892 d wood.		
Synonyms: Additional Information	and is subject to certain labeling require Act. These requirements differ from the required for safety data sheets (SDS).	A States Consumer Product Safety Commission rements under the Federal Hazardous Substances e classification criteria and hazard information The product label also includes other important e, and should always be read in its entirety prior to		
	2. HAZARDS IDENTIF			
Serious Eye Damage/Eye Irritation, Category 1 Germ Cell Mutagenicity, Category 1A Carcinogenicity, Category 2 Specific Target Organ Toxicity (single exposure), Category 3 Aspiration Toxicity, Category 1 Simple Asphyxiant				
GHS Signal Word:	Danger			
GHS Hazard Phrases:	 H223: Flammable aerosol. H280: Containers gas under pressure: H304: May be fatal if swallowed and e H315: Causes skin irritation. H318: Causes serious eye damage. H332: Harmful if inhaled. H335: May cause respiratory irritation. 	enters airways.		
	H336: May cause drowsiness or dizzir H340: May cause genetic defects. H351: Suspected of causing cancer.			
GHS Precaution Phrases:	 H340: May cause genetic defects. H351: Suspected of causing cancer. P201: Obtain special instructions befo P202: Do not handle until all safety pressure 	ness. re use. ecautions have been read and understood. ben flames/hot surfaces No smoking. or any other ignition source. bierce or burn, even after use. s/spray. andling.		

	P280: Wear protective gloves/protective clothing/eye protection/face protection.
GHS Response Phrases:	P281: Use personal protective equipment as required. P301+310: IF SWALLOWED: Immediately call a POISON CENTER or doctor/physician.
	P302+352: IF ON SKIN: Wash with plenty of soap and water.
	P304+340: IF INHALED: Remove victim to fresh air and keep at rest in a position
	comfortable for breathing.
	P305+351+338: IF IN EYES: Rinse cautiously with water for several minutes. Remove
	contact lenses, if present and easy to do. Continue rinsing. P308+313: IF exposed or concerned: Get medical attention/advice.
	P310: Immediately call a POISON CENTER or doctor/physician.
	P321: Specific treatment see label.
	P331: Do NOT induce vomiting.
	P332+313: If skin irritation occurs, get medical advice/attention.
	P362: Take off contaminated clothing and wash before re-use.
GHS Storage and Disposal	P403+233: Store container tightly closed in well-ventilated place.
Phrases:	P405: Store locked up.
	P410+403: Protect from sunlight and store in well-ventilated place. P412: Do not expose to temperatures exceeding 50 °C/122 °F.
	P501: Dispose of contents/container according to local, state and federal regulations.
	Flammability
Hazard Rating System:	HEALTH * 2
	FLAMMABILITY 4
	PHYSICAL 0 Health
HMIS:	PPE X NFPA: Special Hazard
OSHA Regulatory Status:	This material is classified as hazardous under OSHA regulations.
Potential Health Effects	EYE CONTACT:
(Acute and Chronic):	Will cause eye irritation.
	SKIN CONTACT:
	Prolonged or repeated contact can result in defatting and drying of the skin which may
	result in skin irritation and dermatitis (rash).
	INHALATION:
	Headaches, dizziness, nausea, central nervous system depression, decreased blood
	pressure, changes in heart rate and cyanosis may result from over-exposure to vapor.
	Prolonged inhalation may be harmful. May cause respiratory tract irritation.
	INGESTION:
	Moderately toxic. May be harmful if swallowed.
	CHRONIC HAZARDS:
	Chronic overexposure to xylene may cause damage to the formed elements of blood
	(e.g., red cells, which carry oxygen). Reports indicate that repeated and prolonged
	overexposure of the eyes to xylene vapor may cause corneal injury. Repeated,
	excessive exposures may cause kidney and liver damage. Reports have associated
	repeated and prolonged overexposure to solvents with neurological and other physiological damage. Intentional misuse by deliberately concentrating and inhaling
	solvents may be harmful or fatal.
	PRIMARY ROUTES OF ENTRY:
	skin contact, inhalation, ingestion, eye contact
l.,	

TARGET ORGANS AND SYSTEMS:

liver, kidneys, circulatory system, central nervous system

Medical Conditions Generally Diseases of the skin.

Aggravated By Exposure:

3. COMPOSITION/INFORMATION ON INGREDIENTS

CAS #	Hazardous Components (Chemical Name)	Concentration	RTECS #
1330-20-7	Xylene (mixed isomers) {Benzene, dimethyl-}	30.0 -50.0 %	ZE2100000
142-82-5	Heptane	20.0 -40.0 %	MI7700000
68476-86-8	Liquified petroleum gas, sweetened {propane, isobutane, n-butane}	<35.0 %	NA
100-41-4	Ethylbenzene {Ethylbenzol; Phenylethane}	<15.0 %	DA0700000
112945-52-5	Silica, amorphous treated {Fumed silica}	< 5.0 %	VV7310000
1317-65-3	Limestone {Calcium carbonate; Pigment white 18; Lithograpic stone}	< 5.0 %	EV9580000

Additional Chemical

Specific percentage of composition is being withheld as a trade secret.

4. FIRST AID MEASURES

Emergency and First Aid Skin: Procedures: Remove contaminated clothing. Immediately wash skin thoroughly with large amounts of water and mild soap, if available. Seek medical attention if irritation develops or persists. Do not use organic solvent to remove product from skin. Eyes: Immediately begin to flush eyes with water, remove any contact lens. Continue to flush the eyes for at least 15 minutes. Seek medical attention. Inhalation: Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Get immediate medical attention. Ingestion: If swallowed, do NOT induce vomiting. Seek immediate medical attention. Call a physician or poison control center immediately. Never give anything by mouth to an unconscious person. See Potential Health Effects. Signs and Symptoms Of Exposure: Note to Physician: Treatment of overexposure should be directed at the control of symptoms and the clinical condition of the patient.

	5. FIRE FIGHTING MEASURES
Flammability Classification:	Level 3 Aerosol
Flash Pt:	80.00 F
Explosive Limits:	LEL: 1 % UEL: 6.7%
Autoignition Pt:	No data.
Suitable Extinguishing Media	:Use carbon dioxide, dry powder, water spray, or foam.
Unsuitable Extinguishing Media:	Water jet.
Fire Fighting Instructions:	As in any fire, wear self-contained breathing apparatus pressure-demand, MSHA/NIOSI approved or equivalent) and full protective gear. Containers can build up pressure if exposed to heat (fire). Storage containers exposed to fire should be kept cool with wate spray to prevent pressure build-up. Stay away from containers that have been exposed to intense heat or flame. Water runoff can cause environmental damage. Dike and collect water used to fight fire.
Flammable Properties and Hazards:	FLASHPOINT OF LIQUID: 80 F
	FLASHPOINT OF PROPELLANT: -138.23 F
	EXTREMELY FLAMMABLE LIQUID AND VAPOR.
	Vapors are heavier than air and may travel along the ground or be moved by ventilation and ignited by heat, sparks, flame, and other ignition sources distant from material handling point.
	6. ACCIDENTAL RELEASE MEASURES
Steps To Be Taken In Case Material Is Released Or Spilled:	Extremely flammable liquid and vapors. Vapors are heavier than air. Vapors are heavier than air and may travel along the ground or be moved by ventilation and ignited by hear sparks, flame, and other ignition sources.
	Isolate the immediate area. Prevent unauthorized entry. Eliminate all sources of ignition in area and downwind of the spill area. Stay upwind, out of low areas, and ventilate closed spaces before entering. All equipment used when handling this product must be grounded or non-sparking. Do not touch or walk through spilled material. Stop leak if you can do so without risk. Prevent entry into waterways, sewers, or confined areas. A vapor suppressing foam may be used to reduce vapors. Absorb or cover with dry earth sand, or other non-combustible material and transfer to compatible containers. For larg spills, dike ahead of the spill.
	7. HANDLING AND STORAGE
Precautions To Be Taken in Handling:	Read carefully all cautions and directions on product label before use. Since empty container retains residue, follow all label warnings even after container is empty. Dispose of empty container according to all regulations. Do not reuse this container.
	Do not use this product near any source of heat, sparks, open flame, furnace areas, pilo lights, stoves, etc.
	Do not use in small enclosed spaces, such as basements and bathrooms. Vapors can accumulate and explode if ignited.
	Avoid contact with eyes and prolonged skin contact. Avoid breathing vapors.
Licensed to W.M. Barr and Company:	

Keep out of reach of children.

Precautions To Be Taken in Storing:

Store in a cool, dry place. Do not store near flames or at elevated temperatures above 120 F. Protect against freezing. Do not store in direct sunlight.

Segregate from metals, lyes, oxidants, and from foods and animal feeds.

8. EXPOSURE CONTROLS/PERSONAL PROTECTION

CAS #	Partial Chemica	I Name	OSHA TWA	ACGIH TWA	Other Limits
1330-20-7	Xylene (mixed is dimethyl-}	omers) (Benzene,	PEL: 100 ppm	TLV: 100 ppm STEL: 150 ppm	No data.
142-82-5	Heptane		PEL: 500 ppm	TLV: 400 ppm	No data.
68476-86-8	Liquified petroleu {propane, isobuta	um gas, sweetened ane, n-butane}	No data.	No data.	No data.
100-41-4	Ethylbenzene {E Phenylethane}	Ethylbenzol;	PEL: 100 ppm	TLV: 100 ppm STEL: 125 ppm	No data.
112945-52-5	Silica, amorphou silica}	s treated {Fumed	No data.	No data.	No data.
1317-65-3	Limestone {Calc Pigment white 18	ium carbonate; 3; Lithograpic stone}	PEL: 15 (dust); 5 (resp.) mg/m3	No data.	No data.
Respiratory (Specify Typ	• •		vith inadequate ventilation SH approved respirator f	•	
		ventilation under e appropriate TLV.	led work places and othe engineered air control sys	stems designed to preve	
			not provide protection ag	-	
Eye Protectio		against potential e recommended wh more protection to	nemical goggles, or face s eye contact, irritation, or in en splashing or spraying help reduce chemical co as much resistance to the	njury. Chemical goggle of chemical is possible ontact to the face and e	es or face shields are A faceshield provides yes.
Protective G	ioves:	materials such as chemicals being u	nitrile may provide protections sed and conditions of use s contaminated with proc	ction. Glove selection s e. Consult your glove s	should be based on supplier for additional
Other Protec	tive Clothing:		n methods can dictate us able aprons, etc., to minin		ve safety equipment,
Engineering (Ventilation e			osures, local exhaust ven evels below recommende	•	ering controls to
		where vapors can enclosed areas. N open all windows the work area. If	quate ventilation to preve accumulate and concent Whenever possible, use o and doors and maintain a strong odor is noticed or y tering STOP ventilation air.	trate, such as basemen outdoors in an open air a cross ventilation of mo you experience slight d	ts, bathrooms or small area. If using indoors oving fresh air across izziness, headache,

Licensed to W.M. Barr and Company: MIRS MSDS, (c) A V Systems, Inc.

Work/Hygienic/Maintenance Practices: Wash hands thoroughly after use and before eating, drinking, or smoking. Do not eat, drink, or smoke in the work area. Discard any clothing or other protective equipment that cannot be decontaminated. Facilities storing or handling this material should be equipped with an emergency eyewash and safety shower. 9. PHYSICAL AND CHEMICAL PROPERTIES Physical States: [X] Gas [X] Liquid [] Solid Appearance and Odor: Opaque, off-white (possibly varying colors) paste with a solvent-like odor. Melting Point: No data. Fash Pt: 80.00 F Explosive Limits: LEL: 1 % LEL: 1 % UEL: 6.7% Specific Gravity (Water =1): No data. Density: 0.98 Vapor Pressure (vs. Air or mm Hg): No data. Solubility in Water: slight Percent Volatile: 87.0 % Conditions To Avoid - No data available. Instability: Unstable [] Stable [X] Conditions To Avoid - No data available. Instability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Becomposition Or carbon monoxide, carbon dioxide Byproducts:			
Do not eat, drink, or smoke in the work area. Discard any clothing or other protective equipment that cannot be decontaminated. Facilities storing or handling this material should be equipped with an emergency eyewash and safety shower. 9 PHYSICAL AND CHEMICAL PROPERTIES Physical States: [X] Gas [X] Liquid [] Solid Appearance and Odor: Opaque, off-white (possibly varying colors) paste with a solvent-like odor. Melting Point: No data. Boiling Point: No data. Boiling Point: No data. Boiling Point: No data. Flash Pt: 80.00 F Explosive Limits: LEL: 1 % Density: 0.98 Vapor Pressure (vs. Air or mm Hg): No data. Solubility in Water: slight Percent Volatile: 87.0 % Other Stabel [] Stabe [X] Conditions To Avoid - No data available. Instability: Instabel [] Stabe [X] Instabel[II: No data available. Instability: No data available. Instability: No data available. Instability: Notata available. <td< th=""><th></th><th>Wash hands thoroughly after use and before eating, drinking, or smoking.</th><th></th></td<>		Wash hands thoroughly after use and before eating, drinking, or smoking.	
Facilities storing or handling this material should be equipped with an emergency eyewash and safety shower. 9 PHYSICAL AND CHEMICAL PROPERTIES Physical States: [X] Gas [X] Liquid] Solid Appearance and Odor: Opaque, off-white (possibly varying colors) paste with a solvent-like odor. Melting Point: No data. Boiling Point: 277.00 F - 315.00 F Autoignition Pt: No data. Flash P1: 80.00 F Explosive Limits: LEL: LEL: 1 % UBensity: 0.98 Vapor Pressure (vs. Air or No data. Bolubility in Water: slight Percent Volatile: 87.0 % Destry (vs. Air = 1): > 1 Exaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % Destry: Unstable [] Stable[X] No data available. No data available. Instability: Instable. Instability: No data available. Instability: No data available. Instability: No data available.	Practices:	Do not eat, drink, or smoke in the work area.	
eyewash and safety shower. 9. PHYSICAL AND CHEMICAL PROPERTIES Physical States: [X] Gas [X] Liquid [] Solid Appearance and Odor: Opaque, off-white (possibly varying colors) paste with a solvent-like odor. Melting Point: No data. Boiling Point: 277.00 F - 315.00 F Autoignition Pt: No data. Boiling Point: 277.00 F - 315.00 F Autoignition Pt: No data. Explosive Limits: LEL: Explosive Limits: LEL: Explosive Limits: LEL: Specific Gravity (Water = 1): No data. Density: 0.98 Vapor Pressure (vs. Air or mo data. Solubility in Water: slight Percent Volatile: 87.0 % Other Stable [] Stability: Unstable [] Stability: Unstable [] Stability: No data available. Instability: Strong oxidizers, acids, and ba		Discard any clothing or other protective equipment that cannot be decontaminat	ted.
eyewash and safety shower. 9. PHYSICAL AND CHEMICAL PROPERTIES Physical States: [X] Gas [X] Liquid [] Solid Appearance and Odor: Opaque, off-white (possibly varying colors) paste with a solvent-like odor. Melting Point: No data. Boiling Point: 277.00 F - 315.00 F Autoignition Pt: No data. Boiling Point: 277.00 F - 315.00 F Autoignition Pt: No data. Explosive Limits: LEL: Explosive Limits: LEL: Explosive Limits: LEL: No data. 0.98 Vapor Pressure (vs. Air or mo data. Solubility in Water: slight Percent Volatile: 87.0 % On data available. Instability: Unstable [] Stability: Unstable [] Stability: No data available. Instability: No data available. Instability: No data available. Instability: No data available. Precent Volatile To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide		Eacilities storing or handling this material should be equipped with an emergence	N
Physical States: [X] Gas [X] Liquid [] Solid Appearance and Odor: Opaque, off-white (possibly varying colors) paste with a solvent-like odor. Metting Point: No data. Boiling Point: 277.00 F - 315.00 F Autoignition Pt: No data. Flash Pt: 80.00 F Explosive Limits: LEL: 1% Uspecific Gravity (Water = 1): No data. Density: 0.98 Vapor Pressure (vs. Air or mm Hg): No data. Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % Stability: Unstable [] Stability: No data available. Instability: Incompatibility - Materials To Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Will occur [] Will not occur [X]			<i>,</i> y
Physical States: [X] Gas [X] Liquid [] Solid Appearance and Odor: Opaque, off-white (possibly varying colors) paste with a solvent-like odor. Metting Point: No data. Boiling Point: 277.00 F - 315.00 F Autoignition Pt: No data. Flash Pt: 80.00 F Explosive Limits: LEL: 1% Uspecific Gravity (Water = 1): No data. Density: 0.98 Vapor Pressure (vs. Air or mm Hg): No data. Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % Stability: Unstable [] Stability: No data available. Instability: Incompatibility - Materials To Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Will occur [] Will not occur [X]	0		
Appearance and Odor: Opaque, off-white (possibly varying colors) paste with a solvent-like odor. Metting Point: No data. Boiling Point: 277.00 F - 315.00 F Autoignition Pt: No data. Flash Pt: 80.00 F Explosive Limits: LEL: 1 % UEL: 6.7% Specific Gravity (Water = 1): No data. Density: 0.98 Vapor Pressure (vs. Air or mm Hg): No data. Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % Stability: Unstable [] Stability: No data available. Instability: No data available. Instability: No data available. Paradous Decomposition Or carbon monoxide, carbon dioxide Sporoducts: Possibility of Hazardous Will occur [] Will not occur [X]			
Metting Point: No data. Boiling Point: 277.00 F - 315.00 F Autoignition Pt: No data. Flash Pt: 80.00 F Explosive Limits: LEL: 1 % UEL: 6.7% Specific Gravity (Water = 1): No data. Density: 0.98 Vapor Pressure (vs. Air or mm Hg): No data. Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % IO. STABILITY AND REACTIVITY Stability: Unstable [] Stability: No data available. Instability: Instable [] Stability: No data available. Instability: Incompatibility - Materials To Krong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]			
Boiling Point: 277.00 F - 315.00 F Autoignition Pt: No data. Flash Pt: 80.00 F Explosive Limits: LEL: 1 % UEL: 6.7% Specific Gravity (Water = 1): No data. Density: 0.98 Vapor Pressure (vs. Air or No data. mm Hg): Vapor Density (vs. Air = 1): Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % IOL STABILITY AND REACTIVITY Stability: Unstable [] Stability: Unstable [] Stability: No data available. Instability: No data available. Instability: Incompatibility - Materials To Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Will occur [] Will not occur [X]			
Autoignition Pt: No data. Flash Pt: 80.00 F Explosive Limits: LEL: 1 % UEL: 6.7% Specific Gravity (Water = 1): No data. Density: 0.98 Vapor Pressure (vs. Air or mm Hg): No data. Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % 10. STABILITY AND REACTIVITY Stability: Unstable [] Stable [X] Conditions To Avoid - No data available. Instability: Incompatibility - Materials To Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Will occur [] Will not occur [X]			
Flash Pt: 80.00 F Explosive Limits: LEL: 1 % UEL: 6.7% Specific Gravity (Water = 1): No data. Density: 0.98 Vapor Pressure (vs. Air or No data. No data. mm Hg): Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % 10. STABILITY AND REACTIVITY Stability: Unstable [] Stable [X] Conditions To Avoid - No data available. Instability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]	-		
Explosive Limits: LEL: 1 % UEL: 6.7% Specific Gravity (Water = 1): No data. Density: 0.98 Vapor Pressure (vs. Air or modata. mm Hg): No data. Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % 10. STABILITY AND REACTIVITY Stability: Unstable [] Stability: Unstable [] Stability: No data available. Instability: No data available. Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Will occur [] Possibility of Hazardous Will occur []			
Specific Gravity (Water = 1): No data. Density: 0.98 Vapor Pressure (vs. Air or No data. mm Hg): Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % ID. STABILITY AND REACTIVITY Stability: Unstable [] Stability: Unstable [] Stability: No data available. Instability: No data available. Instability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]			
Density: 0.98 Vapor Pressure (vs. Air or No data. mm Hg): Vapor Density (vs. Air = 1): Vapor Density (vs. Air = 1): No data. Solubility in Water: slight Percent Volatile: 87.0 % 10. STABILITY AND REACTIVITY Stability: Unstable [] Stability: Unstable [] Stability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur []			
Vapor Pressure (vs. Air or No data. mm Hg): Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % IO. STABILITY AND REACTIVITY Stability: Unstable [] Stable [X] Conditions To Avoid - No data available. Instability: Instabile. Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Will occur [] Will not occur [X]			
mm Hg): Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % IO. STABILITY AND REACTIVITY Stability: Unstable [] Stability: Unstable [] Stability: No data available. Instability: No data available. Instability: No data available. Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]	-		
Vapor Density (vs. Air = 1): > 1 Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % 10. STABILITY AND REACTIVITY Stability: Unstable [] Stable [X] Conditions To Avoid - No data available. Instability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]			
Evaporation Rate: No data. Solubility in Water: slight Percent Volatile: 87.0 % ID. STABILITY AND REACTIVITY Stability: Unstable [] Stability: Unstable [] Stability: No data available. Instability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]		>1	
Solubility in Water: slight Percent Volatile: 87.0 % 10. STABILITY AND REACTIVITY Stability: Unstable [] Stable [X] Conditions To Avoid - No data available. Instability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X] Vill not occur [X]		No data.	
Percent Volatile: 87.0 % 10. STABILITY AND REACTIVITY Stability: Unstable [] Stable [X] Conditions To Avoid - No data available. Instability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]	-	slight	
Stability: Unstable [] Stable [X] Conditions To Avoid - No data available. Instability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Will occur [] Will not occur [X]		-	
Conditions To Avoid - No data available. Instability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]		10. STABILITY AND REACTIVITY	
Instability: Incompatibility - Materials To Strong oxidizers, acids, and bases. Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]	Stability:	Unstable [] Stable [X]	
Avoid: Hazardous Decomposition Or carbon monoxide, carbon dioxide Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]		No data available.	
Byproducts: Possibility of Hazardous Will occur [] Will not occur [X]		Strong oxidizers, acids, and bases.	
		r carbon monoxide, carbon dioxide	
Reactions:	Possibility of Hazardous Reactions:	Will occur [] Will not occur [X]	
Conditions To Avoid - No data available. Hazardous Reactions: Image: Conditional Conditiona Conditional Conditionae		No data available.	
	Licensed to W.M. Barr and Company:	MIRS MSDS, (c) A V Systems, Inc.	GHS form

		11. TOXICOLOGICAL IN	NFORMA	ATION		
Toxicologica	Information:	Material has not been tested as who	ole. Refer to	section 2 for	acute and ch	nronic effects.
Carcinogenicity/Other Information:		CAS# 1330-20-7: Acute toxicity, LC50, Inhalation, Rat Result: Behavioral: Muscle contraction or s Lungs, Thorax, or Respiration:Othe - Raw Material Data Handbook, Vol Printing Ink Research Institute, Frar Bethlehem, PA 18015, Vol/p/yr: 1,12	pasticity. r changes. .1: Organic ncis McDona	Solvents, 19		
		Standard Draize Test, Eyes, Specie Result: Behavioral: General anesthetic. Behavioral: Somnolence (general de Behavioral: Irritability. - "Sbornik Vysledku Toxixologickehe Vedoucicn P, Marhold, J.V., Institut Prumyclu Praha Czechoslovakia, Ve	epressed ac o Vysetreni Pro Vychov	ctivity). Latek A Pripr vu Vedoucicn	avku," , Instit	•
CAS# 100-41-4: Tumorigenic Effects:, TCLo, Inhalation, Rat, 750.0 ppm. Result: Tumorigenic: Carcinogenic by RTECS criteria. Kidney, Ureter, Bladder: Tumors. Standard Draize Test, Eyes, Species: Rabbit, 500.0 MG, Severe. Result: Effects on Fertility: Post-implantation mortality (e.g., dead and/or resor total number of implants). Effects on Fertility: Litter size (e.g.; # fetuses per litter; measured befor Effects on Embryo or Fetus: Fetotoxicity (except death, e.g., stunted fetor)		nd/or resorbed ured before b stunted fetus	virth).			
	 American Journal of Ophthalmology., Ophthalmic Pub. Co., 435 N. Michigan Suite 1415, Chicago, IL 60611, Vol/p/yr: 29,1363, 1946 IARC 2B - Possibly Carcinogenic to Humans IARC 3: Not Classifiable as to Carcinogenicity in Humans. ACGIH A3 - Confirmed Animal Carcinogen with Unknown Relevance to Huma ACGIH A4 - Not Classifiable as a Human Carcinogen. 		-			
CAS #	Hazardous Con	nponents (Chemical Name)	NTP	IARC	ACGIH	OSHA
1330-20-7		omers) {Benzene, dimethyl-}	n.a.	3	A4	n.a.
142-82-5	Heptane		n.a.	n.a.	n.a.	n.a.
68476-86-8		um gas, sweetened {propane, isobutane,		n.a.	n.a.	n.a.
100-41-4	Ethylbenzene {	Ethylbenzol; Phenylethane}	n.a.	2B	A3	n.a.
112945-52-5	Silica, amorphou	is treated {Fumed silica}	n.a.	n.a.	n.a.	n.a.
1317-65-3	Limestone {Calc	cium carbonate; Pigment white 18;	n.a.	n.a.	n.a.	n.a.

	12. ECOLOGICA	L INFORMA	TION		
General Ecolo Information:	ogical Material has not been tested	l as a whole.			
	13. DISPOSAL C	ONSIDERAT	IONS		
Waste Dispos	al Method: Dispose of in accordance wi	th local, state, and	l federal laws.		
	Do not place material in general trash.				
	Do not allow material to ente	er bodies of water	or sewers.		
	14. TRANSPOR	T INFORMA ⁻	ΓΙΟΝ		
LAND TRANS	PORT (US DOT):				
DOT Prop DOT Haza UN/NA Nu		ORM-D			
MARINE TRA	ANSPORT (IMDG/IMO):				
	O Shipping Name: UN1950, Aerosols, flam	mable, 2.1, Ltd. C	tty.		
	ORT (ICAO/IATA):	mable 21 ltd O	h. <i>,</i>		
	ICAO/IATA Shipping Name: UN1950, Aerosols, flammable, 2.1, Ltd. Qty.				
Information:	Additional TransportThe supplier may apply one of the following exceptions: Combustible Liquid, ConsumerInformation:Commodity, Limited Quantity, Viscous Liquid, Does Not Sustain Combustion, or others,				
as allowed under 49CFR Hazmat Regulations. Please consult 49CFR Subchapter C to					
	ensure that subsequent ship		•	δ.	
	15. REGULATOR		TION		
-	perfund Amendments and Reauthorization Act	-			
CAS # 1330-20-7	Hazardous Components (Chemical Name) S. 302 (EHS) S. 304 RQ S. 313 (TRI) Vulges (mixed isomers) (Benzone dimethyl.) No. Voc. 100 LB Voc.				
1330-20-7	Xylene (mixed isomers) {Benzene, dimethyl-} No Yes 100 LB Yes		No		
68476-86-8	Heptane	No	No		
00470-00-0	Liquified petroleum gas, sweetened {propane, No No No No				
100-41-4	Ethylbenzene {Ethylbenzol; Phenylethane}	No	Yes 1000 LB	Yes	
112945-52-5	Silica, amorphous treated {Fumed silica}	No	No	No	
1317-65-3	Limestone {Calcium carbonate; Pigment white 18; Lithograpic stone}	No	No	No	
This material meets the EPA[X] Yes [] NoAcute (immediate) Health Hazard'Hazard Categories' defined[X] Yes [] NoChronic (delayed) Health Hazardfor SARA Title III Sections[X] Yes [] NoFire Hazard311/312 as indicated:[X] Yes [] NoSudden Release of Pressure Hazard[] Yes [X] NoReactive Hazard					
CAS #	Hazardous Components (Chemical Name)	Other US EPA o	r State Lists		
1330-20-7	Xylene (mixed isomers) {Benzene, dimethyl-}	CAA HAP,ODC: Inventory; CA P	HAP; CWA NPDES ROP.65: No	: Yes; TSCA: Yes -	
142-82-5	Heptane	Inventory, 4 Test	No; CWA NPDES: N , 8A PAIR; CA PRO	P.65: No	
68476-86-8	Liquified petroleum gas, sweetened {propane,	CAA HAP,ODC:	No; CWA NPDES: N	No; TSCA: Yes -	
Licensed to W.M.	Barr and Company: MIRS MSDS, (c) A V Systems, Inc.			GHS format	

Page: 9 Printed: 04/15/2015 Revision: 04/15/2015 Supersedes Revision: 03/20/2015

	isobutane, n-butane}	Inventory; CA PROP.65: No
100-41-4	Ethylbenzene {Ethylbenzol; Phenylethane}	CAA HAP,ODC: HAP; CWA NPDES: Yes; TSCA: Yes - Inventory, 4 Test; CA PROP.65: Yes
112945-52-5	Silica, amorphous treated {Fumed silica}	CAA HAP,ODC: No; CWA NPDES: No; TSCA: No; CA PROP.65: No
1317-65-3	Limestone {Calcium carbonate; Pigment white 18; Lithograpic stone}	CAA HAP,ODC: No; CWA NPDES: No; TSCA: Yes - Inventory; CA PROP.65: No

Regulatory Information:

	16. OTHER INFORMATION
Revision Date:	04/15/2015
Preparer Name:	W.M. Barr EHS Dept (901)775-0100
Additional Information About This Product:	No data available.
Company Policy or Disclaimer:	The information contained herein is presented in good faith and believed to be accurate as of the effective date shown above. This information is furnished without warranty of any kind. Employers should use this information only as a supplement to other information gathered by them and must make independent determination of suitability and completeness of information from all sources to assure proper use of these materials and the safety and health of employees. Any use of this data and information must be determined by the user to be in accordance with applicable federal, state and local laws and regulations.